



Calço Tampa Traseira  
do Cambio  
321.262.0862



Calço Encosto Moringa  
do Cambio  
312.262.5362



Calço Encosto Moringa  
do Cambio  
317.262.5262



Arruela Mola  
Válvula Cabeçote  
906.990.0040



Arruela Trava da Ré  
Cambio 608 D  
385.263.0062



Arruela Trava  
Cubo Traseiro 1113  
321.356.0173



Arruela Trava  
Cubo Traseiro 1313  
345.356.0073



Arruela Manga  
Eixo 1113/ 2213  
327.332.1662




Arruela Cubo  
Traseiro 1113  
321.356.0152



Arruela Cubo Tras.  
1113/1513/2013  
345.356.0052



Trava Pino  
Garrafinha do Patim  
302.994.0109



Porca Rápida 4,2mm  
000.994.0445



Reparo Estabilizador  
Diant. Sprinter D97  
901.323.0288



Suporte GNV



Suporte para TV